

## M300-30 / M300-30/P

### CHARACTERISTICS

|                                   |   |
|-----------------------------------|---|
| Microprocessor                    | INTEL 486 SX M300-30<br>INTEL 486 DX2 M300-30/P   |
| Clock                             | 25 MHz  |
| Architecture                      | AT  |
| Memory                            | From 4 MB to 36 MB on the motherboard<br>Bank 0 4 MB, 1MB x 4 bit chips soldered<br>Bank 1 Four sockets that can accommodate the following SIMMs<br>1 M x 9 <b>EXM 27-820</b> (2 MB)<br>4 M x 9 <b>EXM 27-821</b> (8 MB)<br>Bank 2 Same as bank 1<br><b>NOTE:</b> Two memory kits are always needed to expand memory (4 SIMMs)  |
| Video memory                      | 1 MB - Eight DRAM 256x4 - 70 ns chips   |
| Memory access                     | 80 ns   |
| Coprocessor for M300-30 only      | 25 MHz INTEL 487 SX<br>Overdrive Coprocessor  |
| Floppy Disk                       | 1.2 MB 5.25" Panasonic JU 475-3-4-5<br>1.2 MB 5.25" Toshiba ND 08 DE<br>1.44 MB 3.5" Panasonic JU-257<br>1.44 MB 3.5" Sony MP-F17 / MITSUMI D359T3<br>1.44 MB Mitsubishi MF355C<br>1.44 MB YE DATA YD-702B / 702D<br>2.88 MB Sony MP-F40W   |
| Hard Disk                         | 40 MB QUANTUM Pioneer ELS42 AT<br>85 MB W.D. Caviar 280<br>85 MB CONNER CP30084E<br>85 MB QUANTUM Pioneer ELS85 AT<br>120 MB QUANTUM Pioneer ELS127 AT<br>170 MB CONNER CP30174E<br>170 MB QUANTUM Pioneer ELS170 AT<br>170 MB W.D. AC1170<br>210 MB QUANTUM LPS240 AT<br>210 MB CONNER CP30256 / CP30204<br>240 MB W.D. AC2250-14F<br>240 MB CONNER CP30254<br>340 MB CONNER CP3304 / CP3364<br>340 MB W.D. AC2340<br>510 MB CONNER CP3504 / CP3544<br>510 MB CONNER CP30544 |
| Streaming Tape                    | 80/120 MB IRWIN 287 with floppy interface<br>150 MB Wangtek with SCSI interface - This Streaming Tape drive requires the SCSI ASC1/A controller   |
| Slots                             | Four 16-bit connectors on the expansion bus   |
| Video controller                  | Integrated Super VGA WD90C31  |
| Integrated HDU and FDU controller | Floppy disk controller: 87312<br>HDU interface: MSI buffer and logic gates  |
| Mouse                             | PS/2- and AT-compatible   |
| Keyboard                          | 101/102-key ANK 26-101, ANK 26-102  |

### MOTHERBOARD

|         |                            |
|---------|----------------------------|
| BA356:  | M300-30                    |
| BA366:  | M300-30                    |
| BA2018: | M300-30 with on-socket CPU |
| BA2008: | M300-30/P                  |
| BA2025: | M300-30 no Flash EPROM     |
| BA2030  | M300-30 4-layer P.C.       |
| BA2031  | M300-30/P 4-layer P.C.     |

36

### BIOS

The ROM BIOS is a FLASH EPROM. It is provided on diskettes and must be copied into Flash EPROM.

Latest level: 2.01

Board BA 2025 has an EPROM instead of a FLASH EPROM

### EXPANSION BUS

IN 138  
IN 2000

### POWER SUPPLY

PS11 R 220 V  
PS11 R 115 V  
  
PS11 AR 220V  
PS11 AR 110V

**MOTHERBOARD**

|         | LEVEL      | D.R.S. CODE | ROM BIOS  | NOTES  |
|---------|------------|-------------|---|--|
| BA356   | Nasc.      | 553094 N    | The ROM BIOS is a FLASH EPROM. The BIOS code is supplied on diskettes and must be copied into Flash EPROM.<br>Rev. 1.03 | M300-30 system board with 4 MB of soldered memory<br>To see what components are on this board, refer to the table listing the integrated controllers.  |
|         | Lev. 01 MI |             |   | This board is replaced by BA 366 which offers the same functions in addition to recuperating the PCB trimmings of the previous board.  |
|         | Lev. 01 SI |             |   | Rev. 1.03  |
| BA366   | Nasc.      |             | Rev. 1.03   | Replaces BA 356 but maintains the same components and functions  |
|         | Lev. 01    |             | Rev. 1.04   | <ul style="list-style-type: none"> <li>- The keyboard controller socket is removed since this controller is soldered directly to the system board.</li> <li>- Mask C of component WD90C31 is replaced by Mask F. Consequently a 100 Ohm resistor R77 must be replaced with a 0 Ohm resistor R67.</li> <li>- PAL ESBB at location U530 is replaced by PAL GKDS. This PAL manages the keyboard controller.</li> </ul>  |
|         | Lev. 02    |             |   | Corrects the malfunction of the parallel port on the TAPEEXCHANGE Interpreter external back-up drive.  |
|         | Lev. 03    |             |   | The keyboard and mouse connectors have been replaced with shielded connectors  |
|         | Lev. 04    |             |   | <ul style="list-style-type: none"> <li>- A 100 pF capacitor has been introduced on the MA (1) signal between pin RP13 and pin 1 of R102. This solves the problem of having a Parity Error signalled when using FUJITSU MB814400A-70 dynamic memory chips.</li> <li>- The 87312 component is used as an alternative to the Super I/O 87311 component.</li> <li>- The Flash EPROM socket has been removed to cut costs. This component will be soldered directly on the system board.</li> </ul> |
| Lev. 05 |            |             | Component 87312 is introduced as an alternative to Super I/O component 87311. The S.R.s are updated to Rev. 1.06.       |  |

|        | LEVEL   | D.R.S. CODE | ROM BIOS  | NOTES   |
|--------|---------|-------------|-----------|---|
| BA2018 | Nasc.   |             |           | Motherboard with the CPU installed in the coprocessor socket.   |
|        | Lev. 01 |             |           | <ul style="list-style-type: none"> <li>- The 87312 component is used as an alternative to the Super I/O 87311 component.</li> <li>- To cut costs, the Flash EPROM socket has been removed. This component will be soldered directly on the system board.</li> </ul> |
|        | Lev. 02 |             |           | A 100 pF capacitor has been introduced on the MA (1) signal between pin RP13 and pin 1 of R102. This solves the problem of having a Parity Error signalled when using FUJITSU MB814400A-70 dynamic memory chips.  |
| BA2008 | Nasc.   |             |           | M300-30/P motherboard with the i486 DX2 CPU installed in the coprocessor socket.  |
|        | Lev. 01 |             |           | Corrects the fault of the parallel port on the TAPEEXCHANGE Interpreter external back-up drive.   |
|        | Lev. 02 |             |           | <ul style="list-style-type: none"> <li>- The 87312 component is used as an alternative to the Super I/O 87311 component.</li> <li>- To cut costs, the Flash EPROM socket has been removed. This component will be soldered directly on the system board.</li> </ul> |
|        | Lev. 03 |             |           | A 100 pF capacitor has been introduced on the MA (1) signal between pin RP13 and pin 1 of R102. This solves the problem of having a Parity Error signalled when using FUJITSU MB814400A-70 dynamic memory chips.  |
| BA2025 | Nasc.   |             | Rev. 1.04 | Motherboard with an EPROM instead of a FLASH EPROM  |
|        |         |             |           |   |
| BA2030 | Nasc.   | 588093 R    |           | New 4-layer printed circuit board replacing the BA366.  |
| BA2031 | Nasc.   | 588094 J    |           | New 4-layer printed circuit board replacing the BA2008.   |

**MOTHERBOARD INTEGRATED CONTROLLERS**

| MOTHERBOARD              | INTEGRATED CONTROLLERS  |
|--------------------------|---|
| <p>BA 356<br/>BA 366</p> | <p>CPU In QFP package (soldered on the system board)<br/> <b>i486 SX CPU</b> 25 MHz microprocessor<br/>                     Socket for the <b>i487SX</b> coprocessor or the <b>i486 DX2</b> Overdrive Processor<br/> <b>VL82C486</b> This component integrates the following functions:<br/>                     - DMA controller<br/>                     - Memory controller<br/>                     - Interrupt controller<br/>                     - Timer<br/>                     - Clock generator<br/>                     - System bus controller<br/> <b>8042</b> Keyboard and mouse controller<br/> <b>87312</b> This controller integrates the following functions:<br/>                     - Floppy disk controller<br/>                     - Interface for two serial ports<br/>                     - Parallel port interface<br/>                     - intelligent hard disk interface<br/> <b>WD90C31</b> Super VGA video controller<br/> <b>ICD2023</b> Programmable clock generator<br/> <b>MCCS14681</b> This component implements the following functions:<br/>                     - 128 byte non-volatile RAM with back-up battery<br/>                     - Real Time Clock<br/> <b>BIOS Flash Eprom</b><br/> <b>EYE</b> Allows tests to be run on the video subsystem</p> |
| <p>BA 2018</p>           | <p>This BA has the following differences with respect to the previous two versions:<br/>                     - CPU In PGA package and installed in the numeric coprocessor socket.<br/>                     To install the coprocessor the CPU must be removed<br/>                     - Jumper J28 to configure the system coprocessor.</p>   |
| <p>BA 2008</p>           | <p>This BA is used on the M300-30/P personal computer and differs from the BA 356 and BA 366 in that it configures an i486 DX2 CPU instead of an i486SX CPU. The i486 DX2 CPU is installed in the coprocessor socket. The i486 DX2 CPU has an integrated coprocessor.</p>   |
| <p>BA 2025</p>           | <p>This BA does not have a Flash EPROM but a normal EPROM. As far as everything else is concerned it is identical to BA 356 and BA 366.</p>   |
| <p>BA 2030</p>           | <p>4-layer system board replacing BA366 and BA356. This board has the J35 jumper which is used to change the Super I/O basic address.</p> <ul style="list-style-type: none"> <li>- 25 MHz i486 SX CPU in QFP package (soldered on the system board)</li> <li>- Socket for the i487 SX math coprocessor or the i486 DX2 OverDrive Processor</li> <li>- Flash EPROM</li> </ul>  |
| <p>BA 2031</p>           | <p>4-layer system board replacing the BA2008 on the M300-30/P. This board has the J35 jumper which is used to change the Super I/O basic address.</p> <ul style="list-style-type: none"> <li>- i486 DX2 CPU installed in the coprocessor socket.</li> <li>- The i486 DX2 CPU already has an integrated coprocessor.</li> <li>- Flash EPROM</li> </ul>   |

**BOARDS**

| FUNCTION             | DESCRIPTION      | D.R.S. CODE          | CHARACTERISTICS  |
|----------------------|------------------|----------------------|--|
| CPU system board     | BA356            | 553094 N             | 4 MB for the M300-30                                   |
|                      | BA366            |                      | 4 MB for the M300-30                                   |
|                      | BA2018           |                      | On-socket CPU  |
|                      | BA2008           | 557934 Q             | For the M300-30/P                                      |
|                      | BA2025           |                      | Without Flash EPROM                                    |
|                      | BA2030<br>BA2031 | 588093 R<br>588094 J | 4-layer P.C. for M300-30<br>4-layer P.C. for M300-30/P |
| PS11 R power supply  | 220 V            | 553028 T             |  |
| PS11 AR power supply | 220 V            |                      |  |
| PS11 R power supply  | 115 V            | 553027 J             |  |
| Bus adapter board    | IN138            | 553333 Z             |  |
| Bus adapter board    | IN2000           | 553667 G             |  |

**BUS EXPANSION BOARD**

| NAME    | LEVEL   | NOTES  |
|---------|---------|--|
| IN 138  | Nasc.   |  |
| IN 2000 | Nasc    | Replaces the previous board.   |
|         | Lev. 01 | Seven 200 Ohm 100 pF terminators have been added to correct the incompatibility with the NCU 9143/S and 9141-II boards |

36

**OLIVETTI USER PROGRAM**

This program resides in the hard disk's system regions.

| LEVEL                   | NOTES  |
|-------------------------|--|
| Rel. 1.00.<br>Rel. 1.01 | The readme utility is not available.   |
| Rel. 1.04               | The test on the CPU recognizes the Overdrive Processor, and the management of the keyboard lock feature is improved.   |
| Rev. 1.05               | In this release: <ul style="list-style-type: none"> <li>- The CPU test recognizes and also tests the i486 DX2 processor</li> <li>- The readme test has been modified.</li> <li>- The logo has been modified.</li> <li>- The mouse test has been added</li> <li>- The possibility of configuring high capacity hard disks has been added</li> <li>- The setup.msg and setup.hlp files have been modified.</li> <li>- The serial port test has been modified.</li> <li>- Four serial ports are recognized during the serial port test.</li> <li>- The floppy disk drive test has been modified.</li> </ul> |
| Rev. 1.06               | Alignment with BIOS 2.00. This release was never used.   |
| Rev. 1.07               | Alignment with BIOS 2.00. <ul style="list-style-type: none"> <li>- Configuration of high capacity hard disks</li> <li>- The CPU test recognizes the 80486 DX2 microprocessor.</li> </ul> Tests run on the four serial and parallel ports <ul style="list-style-type: none"> <li>- New 16 and 256 color 800 x 600 video modes.</li> </ul>   |

**OEM USER PROGRAM**

This program resides in the hard disk's system region and is used on OEM M300-30 personal computers.

| <b>LEVEL</b> | <b>NOTES</b>   |
|--------------|--|
| Rel. 1.01    | The readme utility is not available.   |
| Rel. 1.02    | The test on the CPU recognizes the Overdrive Processor, and the management of the keyboard lock feature is improved.   |
| Rev. 1.03    | In this release: <ul style="list-style-type: none"><li>- The CPU test recognizes and tests the i486 DX2 processor.</li><li>- The Readme test has been modified.</li><li>- The logo has been modified.</li><li>- The mouse test has been added.</li><li>- The possibility of configuring high capacity hard disks has been added.</li><li>- The setup.msg and setup.hlp files have been modified.</li><li>- The serial port test has been modified.</li><li>- Four serial ports are recognized during the serial port test.</li><li>- The floppy disk drive test has been modified.</li></ul> |
| Rev. 1.04    | Alignment with BIOS 2.00. This release was never used.   |
| Rev. 1.05    | Alignment with BIOS 2.00. <ul style="list-style-type: none"><li>- Configuration of high capacity hard disks</li><li>- The CPU test recognizes the 80486 DX2 microprocessor.</li><li>- Tests run on the four serial and parallel ports</li><li>- New 16 and 256 color 800 x 600 video modes.</li></ul>  |

**SYSTEM TEST**

| <b>LEVEL</b> | <b>NOTES</b>   |
|--------------|--|
| Rel. 1.00    | In this release there is no test run on the cache of the cpu_dia module and the readme file is missing.  |
| Rel. 1.01    |  |
| Rev. 1.02    | The setup utility and the tests on the hard disk, keyboard and EYE component have been modified.   |
| Rev. 1.03    | In this release: <ul style="list-style-type: none"> <li>- The CPU recognizes and tests the Overdrive Processor.</li> <li>- The Setup utility has been modified.</li> <li>- Hard disk tests have been added.</li> <li>- The Readme file has been added.</li> <li>- The following two subtests have been added to the memory test: <ol style="list-style-type: none"> <li>a) MEMORY STRESS</li> <li>b) TASK SWITCHING WARNING</li> </ol> </li> </ul>   |
| Rev. 1.04    | In this release: <ul style="list-style-type: none"> <li>- The CPU test recognizes and also tests the i486 DX2 processor.</li> <li>- The Readme text has been modified.</li> <li>- The logo has been modified.</li> <li>- The mouse test has been added.</li> <li>- The possibility of configuring high capacity hard disks has been added</li> <li>- The setup.msg and setup.hlp files have been modified.</li> <li>- The serial port test has been modified.</li> <li>- Four serial ports are recognized during the serial port test.</li> <li>- The floppy disk drive test has been modified.</li> </ul> |
| Lev. 1.06    | In this release: <ul style="list-style-type: none"> <li>- The logotype has been changed.</li> <li>- The test on the serial ports has been optimized.</li> <li>- The possibility of configuring high capacity hard disks has been added</li> <li>- The possibility of also entering a password using AZERTY keyboards has been added.</li> </ul>  |

**SYSTEM REGION SET UP**

| <b>LEVEL</b> | <b>NOTE</b>   |
|--------------|---|
| Rel. 1.01    | <p>This System Region SETUP release allows the User Disk to be installed automatically in the hard disk system regions.<br/>It works with MS-DOS 5.0 only and with BIOS rel. 1.02 or later.<br/>This release has the following faults:</p> <ul style="list-style-type: none"> <li>- The help facility of the Copy User Disk utility is missing.</li> <li>- The Readme, Lastinfo and Tecinfo files are missing.</li> <li>- The power on password does not give access to the system regions.</li> <li>- The hard disk tests are run only in the system region partition.</li> <li>- The Parking Heads utility is not available.</li> </ul> |
| Rev. 1.02    | <p>This System Region SETUP revision allows the User Disk to be installed automatically in the hard disk system regions.<br/>The SETUP utility has been modified.<br/>This release has the following faults:</p> <ul style="list-style-type: none"> <li>- The hard disk tests work only if launched from the system region.</li> <li>- The Parking Heads utility is not available</li> </ul>  |
| Rev. 1.03    | <p>This System Region SETUP revision allows the User Disk to be installed automatically in the hard disk system regions.</p> <ul style="list-style-type: none"> <li>- The CPU tests and the Cpu_dia.msg file has been modified.</li> <li>- The Setup utility has been modified.</li> <li>- Hard disk tests have been added.</li> </ul> <p>The Parking Heads utility is not available.</p>   |
| Rev. 1.04    | <p>This System Region SETUP revision allows the User Disk to be installed automatically in the hard disk system regions.</p> <ul style="list-style-type: none"> <li>- The CPU test recognizes the Overdrive Processor.</li> <li>- The Refresh Detect subtest has been modified.</li> </ul> <p>The Parking Heads utility is not available.</p>   |
| Rev. 1.05    | <p>This System Region SETUP revision allows the User Disk to be installed automatically in the hard disk system regions.<br/>This version contains the following new diagnostic tests:</p> <ul style="list-style-type: none"> <li>- Configuration of high capacity hard disks.</li> <li>- Test on the 80486 DX2 microprocessor.</li> <li>- Test on the four serial and parallel ports.</li> <li>- New 16 and 256 color 800 x 600 video modes.</li> </ul>  |
| Rev. 1.06    | <p>This System Region SETUP version allows the User Disk to be installed automatically in the hard disk system regions.<br/>This new version solves the problems with the tests on the serial port caused by the new 87312 component which is used as an alternative to the 87311 component.</p>  |

**POWER SUPPLY UNITS**

| <b>POWER SUPPLY</b> | <b>LEVEL</b> | <b>DESCRIPTION</b>  |
|---------------------|--------------|---|
| PS11 R 110 V        | Lev. 01      | Manufactured by ASTEC - Due to production problems, this power supply was never manufactured at NASC level.   |
| PS11 R 220 V        | Nasc         | Manufactured by ASTEC.  |
|                     | Lev. 01      | To improve the manufacturing process, a capacitor has been added and a resistance replaced.   |
|                     | Lev. 02      | <ul style="list-style-type: none"> <li>- Addition of an L5 inductor near the mains input area to improve the margins over EMI radiofrequency noise.</li> <li>- New printed circuit board to solve the problems caused by random voltage drops.</li> </ul> |
| PS11 R 110 V        | Nasc         | Manufactured by HANTAREX.   |
| PS11 R 220 V        | Nasc         | Manufactured by HANTAREX.   |
| PS11 AR 220 V       | Lev. 01      | Manufactured by ASTEC - Due to production problems, this power supply was never manufactured at NASC level.   |
|                     | Lev. 02      | The J103 jumper has been replaced with a 10 Ohm resistance. This solves the problem with the ripple not complying with the specifications during minimum load conditions on the +5 V line.  |
| PS11 AR 110 V       |              | The evolution of this power supply is the same as the 220 V model.  |
| PS11 AR 110 V       | Nasc         | Manufactured by MAGNETEK.   |
| PS11 AR 220 V       | Nasc         | Manufactured by MAGNETEK.   |

36

**COMPATIBILITY NOTES**

| <b>BOARD OR HW/SW DEVICE</b>   | <b>DESCRIPTION</b>   |
|--|--|
| Streaming Tape USER DISKETTE Rev. 1.02 provided in the STU 26-082/A Kit        | This release makes it possible to install a streaming tape drive on an M400-10 with system board BA 301 capable of managing a 2.88 MB floppy disk drive. |
| Streaming Tape USER DISKETTE Rev. 1.03 Ver. 1 provided in the STU 26-082/A Kit | Version 1.02 of this User Diskette was entering into conflict with the second floppy disk drive. This problem was corrected with ver. 1.03.              |
| Bus expansion board  | Board IN138 is replaced by IN 2000.  |
| 85 MB and 170 MB CONNER and 85 MB W.D. hard disks                              | The 85 MB and 170 MB CONNER hard disks are not compatible with the Western Digital 85 MB hard disks.   |

**SOFTWARE DRIVERS**

| <b>DRIVER</b>                            | <b>NOTES</b>                                 |
|--|--|
| EVD 1.01<br>EVD 1.03 upd 1.0<br>EVD 1.04 | Solves the problems of the previous release. |

**BIOS**

| <b>LEVEL</b> | <b>NOTES</b>  |
|--------------|---|
| Rev 1.02     |   |
| Rev 1.03     | <p>A new entry in the Jump Table allows the User Disk to read the Setup utility's security facility.</p> <p>The following modifications are made:</p> <ul style="list-style-type: none"> <li>- Solved the following: <ul style="list-style-type: none"> <li>- Serial board on an external board</li> <li>- Quick Lock with Windows</li> <li>- Hidden Partition and Network Server Mode</li> <li>- Password lock during POD</li> <li>- Quick Lock in DOS after a key is pressed.</li> </ul> </li> <li>- Modified the management of cache and RAM disable on system board.</li> </ul> |
| Rev. 1.04    | <p>This release is issued to implement a series of modifications made necessary in order to use the dual speed i486 DX2 processor on the M300-30/P.</p> <p>The following modifications are made:</p> <ul style="list-style-type: none"> <li>- The interrupt controller test was modified so that it no longer depends on system speed.</li> <li>- CPU recognition was modified by the addition of a check on the free KBC input buffer before system shutdown.</li> </ul>   |
| Rev. 2.00    | For the M300-30/P. Solves also the problems with the new 800 x 600 video modes in the Windows environment.  |
| Rev. 2.01    | <p>This version solves the following problems:</p> <ul style="list-style-type: none"> <li>- Installation of Windows NT with an 80486 DX2 processor</li> <li>- Norway keyboard</li> <li>- Monitor recognition (being either a high or low resolution monitor) in the OS/2 environment.</li> </ul>  |


**SOFTWARE COMPATIBILITY**

| <b>OPERATING SYSTEMS</b>   | <b>NOTES</b>   |
|--|--|
| IBM DISK Operating System, Ver. 3.30<br>MS-DOS (Compaq)<br>IBM DISK Operating System, Ver. 4.01<br><br>MS-DOS Release 5.0<br>OS/2 Release 2.0<br>OS/2 Release 1.3 SE | An unformatted DSDD disk is required during installation on hard disk. |
| IBM Operating System/2, Ver. 1.10 and 1.20   | PS/2 mouse is not recognized.  |
| IBM Operating System/2 Extended Edition, Ver. 1.10 and 1.20  | PS/2 mouse is not recognized.  |
| INTERACTIVE 386/ix, Ver. 2.02<br>SCO UNIX System V/386, Rev. 3.2.4<br>SCO XENIX 386, Rev. 2.3  |  |
| <b>WINDOWS</b>   |  |
| GEM/3 Desktop, IBM-PC Ver. 3.02<br>MS-WINDOWS /286 Ver. 2.11   | MS-WINDOWS /386 Ver. 2.11<br>MS-WINDOWS 3 Ver. 3.0                     |

**HARDWARE COMPATIBILITY**

|  |   |
|--|---|
| <p><b>MODEMS</b></p> <p>Hayes Smart modem 2400B<br/>                 FAXY PC MAXTER<br/>                 FURY 2400 PC MODEM<br/>                 AT&amp;T 2224 CEO MODEM<br/>                 FURY 2400 MAXTER MODEM<br/>                 FURY 2400 TI/MNP<br/>                 Hayes Smart modem 1200 B</p>   | <p><b>I/O INTERFACE PRODUCTS</b></p> <p>IBM PRINTER ADAPTER (1505200)<br/>                 STB 4-ON THE FLOOR</p>   |
| <p><b>MULTIPOINT</b></p> <p>CHASE AT8<br/>                 COMPUTONE AT 8<br/>                 COMPUTONE AT 16<br/>                 INTEL Bell ICC.6<br/>                 SPECIALIX SI / 8</p>   | <p><b>MOUSE</b></p> <p>IBM PS/2 Mouse (6450350)<br/>                 IBM PS/2 Mouse Serial<br/>                 Logitech Bus Mouse (PF-3F)<br/>                 Logitech 3 button mouse<br/>                 MS-BUS mouse<br/>                 MS-MOUSE serial</p>  |
| <p><b>GRAPHICS PRODUCTS</b></p> <p>AST VGA plus<br/>                 FASTWRITE 1024i<br/>                 FASTWRITE VGA<br/>                 HERCULES GRAPHICS CARD<br/>                 IBM VGA Adapter<br/>                 MATROX PG - 1281<br/>                 MAXON MVGA-16 Adapter<br/>                 ORCHID PRODESIGNER VGA PLUS<br/>                 HERCULES INCOLOR CARD (GB222)<br/>                 PARADISE VGA PRO CARD</p> | <p><b>NETWORKING &amp; LAN PRODUCTS</b></p> <p>10 NET INTERFACE BOARD 200 series<br/>                 3COM Etherlink adapter 3C501<br/>                 3COM Etherlink II adapter 3C503<br/>                 3COM Etherlink plus adapter 3C505<br/>                 3COM Etherlink plus adapter 3C505<br/>                 DECNET PCSA adapter<br/>                 IBM PC NETWORK adapter II<br/>                 IBM TOKEN RING 16/4 adapter<br/>                 IBM TOKEN RING adapter II<br/>                 MADGE AT RING NODE adapter<br/>                 MICOM NP1000 adapter<br/>                 NOVELL NE1000 adapter<br/>                 NOVELL NE2000 adapter</p> |
| <p><b>DISPLAY UNITS</b></p>  |   |
| <p>IBM enhanced graphics monitor 5151<br/>                 IBM color graphics monitor 5153<br/>                 IBM PS/2 Monochrome display 8503<br/>                 IBM PS/2 color display 8512<br/>                 IBM PS/2 color display 8513<br/>                 IBM PS/2 color display 8514<br/>                 NEC MULTISYNC II</p>  | <p>NEC MULTISYNC 2A<br/>                 NEC MULTISYNC 3D<br/>                 NEC MULTISYNC 4D<br/>                 NEC MULTISYNC 5D<br/>                 PHILIPS 7BM749<br/>                 PHILIPS 9CM082</p>   |

**BA356 - BA366 - BA2025 MOTHERBOARD COMPONENTS AND JUMPERS**



36

**JUMPER J25**

Jumper installed                      Soldered CPU disabled  
 Jumper not installed                Soldered CPU enabled \*

**JUMPER J29**

Not used

**JUMPER J15** - System bootstrap from the 25-pin serial port.

Position 2 - 3 \*                      System bootstrap from the serial port.  
 Position 1 - 2                      The system is not bootstrapped from the serial port.  
 The Power On Diagnostics check the position of this jumper; if it is set in position 2-3, the following message is displayed: *Serial Port 0 Security Enabled.*

**JUMPER J18** - System bootstrap from the 9-pin serial port.

Position 2 - 3 \*                      System bootstrap from the serial port.  
 Position 1 - 2                      The system is not bootstrapped from the serial port.  
 The Power On Diagnostics check the position of this jumper; if it is set in position 2-3, the following message is displayed: *Serial Port 0 Security Enabled.*

**JUMPER J14** - BUILT-IN SETUP program

Position 1 - 2        The User program that resides in the hidden partitions of the hard disk and allows the system to be configured, is not run. If system configuration changes, the only way to reconfigure the system is to use the System Test. If this security feature is enabled, the following message will be displayed at the end of the POD: *POD Warning*.

Position 2 - 3 \*     If system configuration has changed, the POD will automatically run the User program that allows the system to be reconfigured.

**JUMPER J16** - Writing to floppy disk drives.

Position 2 - 3        Write operations to floppy disk drives are disabled.

Position 1 - 2 \*     Write operations to floppy disk drives are enabled..

This feature can also be extended to streaming tape drives with floppy disk interface.

**JUMPER J21**

Jumper not installed        Two hard disk drives are installed.

Jumper installed            Only one hard disk drive is installed\*


**JUMPER J20**

To erase the CMOS, short circuit these two solder points.

\* Indicates the default setting.

**NOTE:** BA2025 uses a normal EPROM rather than a Flash EPROM.

**BA2008 MOTHERBOARD For M300-30/P COMPONENTS AND JUMPERS**



36


On BA 2008, the CPU is no longer soldered.  
The i486 DX2 CPU is installed in the coprocessor socket.

The jumpers have the same functions as those on the BA356 and BA366 board with the exception of jumper J25 which is not used.

**JUMPER J25**

Not used.

## BA2018 MOTHERBOARD COMPONENTS AND JUMPERS



On this board the i486 SX CPU is installed in the processor socket. The CPU will need to be removed in order to install the coprocessor.

The jumpers have the same functions as those on the BA356 and BA366 boards with the exception of the new jumper J28, and of jumper J25 which is not used:

### JUMPER J28


Position 1-2            i486 SX processor or OverDrive Coprocessor  
 Position 2-3            i486 SX processor\*

### JUMPER J25

Not used

\* Indicates the default setting.

**BA2030 MOTHERBOARD COMPONENTS AND JUMPERS**




This board is identical to the BA366 and BA356 board with the exception of jumper J35.

**JUMPER J35**

- Position 1-2 Super I/O basic address 398 - 399\*
- Position 2-3 Super I/O basic address 26E - 26F

\* Indicates the default setting.

## BA2031 MOTHERBOARD COMPONENTS AND JUMPERS



The CPU is not soldered on BA2031.  
 The i486 DX2 CPU is installed in the coprocessor socket.

The jumpers on this board have the same functions as those on boards BA356 and BA366 with the exception of the J35 jumper and of the J28 jumper, which is not used.

### JUMPER J35

Position 1-2            Super I/O basic address 398 - 399\*  
 Position 2-3            Super I/O basic address 26E - 26F

### JUMPER J25

Not used

\* Indicates the default setting.

**INTERRUPT LEVELS**

| LEVEL  | NAME  | CONTROL. | FUNCTION                                    |
|--------|-------|----------|---|
| 1      | IRQ0  | 1        | Channel 0 timer OUT                         |
| 2      | IRQ1  | 1        | Keyboard                                    |
| 3 - 10 | IRQ2  | 1        | Interrupt to Controller 1 from Controller 2 |
| 3      | IRQ8  | 2        | Real time clock                             |
| 4      | IRQ9  | 2        | Available                                   |
| 5      | IRQ10 | 2        | Available                                   |
| 6      | IRQ11 | 2        | Available                                   |
| 7      | IRQ12 | 2        | Available                                   |
| 8      | IRQ13 | 2        | Coprocessor                                 |
| 9      | IRQ14 | 2        | Hard disk controller                        |
| 10     | IRQ15 | 2        | Available                                   |
| 11     | IRQ3  | 1        | Serial port 2                               |
| 12     | IRQ4  | 1        | Serial port 1                               |
| 13     | IRQ5  | 1        | Parallel port 2                             |
| 14     | IRQ6  | 1        | Floppy disk controller                      |
| 15     | IRQ7  | 1        | Parallel port 1                             |

**I/O ADDRESS MAP**

| ADDRESS     | FUNCTION                       | ADDRESS       | FUNCTION                   |
|-------------|--------------------------------|---------------|----------------------------|
| 000-01F h   | DMA controller (channels 0-3)  | 2F8-2FF h     | Serial port (COM2)         |
| 020-021F h  | Interrupt controller 1         | 378-37B h     | Parallel port 2 (LPT 2)    |
| 040-043 h   | Timer                          | 3B4-3B5 h     | Video controller           |
| 60 h        | Data keyboard controller       | 3BA h         | Video controller           |
| 61 h        | System B control port          | 3BC h         | Parallel port 1 (LPT 1)    |
| 64 h        | Commands keyboard controller   | 3C0-3CF h     | Video controller           |
| 070 - 071 h | Real time clock, NMI, CMOS RAM | 3D4-3D5 h     | Video controller           |
| 081-08F h   | DMA page registers             | 3DA h         | Video controller           |
| 0A0-0A1 h   | Interrupt controller 2         | 3F0-3F7 h     | Floppy disk controller     |
| 0C0-0DF h   | DMA channels 4-7               | 3F8-3FF h     | COM1 serial port (default) |
| 1F0-1F8 h   | Hard disk drive                | 46E8 h        | VGA control registers      |
| 278-27B h   | Parallel port 3 (LPT 3)        | 8000F0-8000FF | i487 SX coprocessor        |

**36**

**SYSTEM MEMORY MAP**

